Oil Field Environmental Incident Summary

Responsible Party: Cyclone Drilling

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: CHARLESTON 4-22H1

Field Name: BROOKLYN Well File #: 30096

Date Incident:7/20/2015Time Incident:05:00Facility ID Number:County:WILLIAMSTwp: 155Rng: 98Sec: 22Qtr:

Location Description:

Submitted By: Shane Knuchel Received By:

Contact Person: Shane Knuchel

P.O. Box 908

Gillette, WY 82717

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 3 Barrels 3 barrels 3

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/1/2015 Clean Up Concluded: 8/3/2015

Risk Evaluation:

None

Areal Extent:

Approximately 60x20 ft off the south side of location into cultivated field.

Potential Environmental Impacts:

Topsoil and vegetation.

Action Taken or Planned:

Impacted material was removed and will be taken to disposal. Confirmation sampling will occur to ensure adequate clean-up.

Wastes Disposal Location: Prairie Disposal

Agencies Involved: Notified Tamara Cook NDIC by phone on 7/21/2015 at 10:30 AM CT.

Updates

Date: 7/21/2015 Status: Reviewed - Follow-up Required Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, impacted areas off location. Follow-up is required.

Date: 9/2/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 15:501 9/2/2015.

No sign of impacts at the time of inspection. Impacted material and contaminant have been cleaned up.

No followup is necessary.